

10/04/06



Puget Sound Clean Air Agency

Compliance Status Report

110 Union Street, Suite 500
Seattle, WA 98101-2038
Ph: 206.343.8800 / 1.800.552.3565
Fax: 206.343.7522
www.pscleanair.org

Inspection Date: 10/4/06Time: 15:25

Case/Registration No. <u>R# 15019</u>	Name <u>Longview Fibre Co.</u>		Responsible Person, Title <u>Eric Peranttic Mike Anderson</u>	
Site Address <u>5901 E Marginal Way So.</u>	City <u>Seattle</u>	Zip <u>98134</u>	County <u>King</u>	
Mailing Address <u>PO Box 24867</u>	City, State <u>Seattle, WA</u>	Zip <u>98124-0867</u>	Phone <u>(206) 762-7170 ext 262</u>	

- ☐ I observed no violations of our agency's regulations during my inspection in the areas I inspected.
- ☒ I could not make a compliance determination because:
- ☐ I need to consult with others. I will share my conclusions with you either in person, over the phone, or in writing by _____.

☒ I need more information. Please submit the following information by October 14th 06.

NSPS Boiler on-site (40 CFR Part 60 DC)

Please submit the semi-annual Diesel oil usage report for 1/1/06 - 6/30/06 (if not already submitted.) Not required - No oil burned.

Please submit the daily natural gas boiler consumption log August '06

Please confirm that the oil in your diesel oil storage tank complies w/ NOC 6264 Condition #5 0.05% Sulfur limit and Reg I 9.08 fuel oil Standards.

Issued By:

Elizabeth Gelf

Received By:

MM

Date/Time:

10/04/06 15:25

USEPA SF



1259950

Activity Record

Employee Initials Date Completed

1.	MM	VJD 10/23/06
2.		10-26-06
3.		
4.		

Puget Sound Clean Air Agency
110 Union Street, Suite 500
Seattle, WA 98101-2038

Evaluation Report

Reg #: 15019

AFS #: 15019

Status: Active

40 CFR Part 60 Dc

Facility: Longview Fibre Co
Physical Address: 5901 E Marginal Wy S
Seattle 98134
Invoice Address: PO Box 24867
Seattle WA 98124-0867

Personal Protective Equipment Checklist

Determined by Inspector based on
Compliance Manual Policy 101

Worn	Safety Equipment	Req/Op
<input type="checkbox"/>	None	
<input type="checkbox"/>	Hard Hat	
<input type="checkbox"/>	Goggles	
<input type="checkbox"/>	Safety Glasses	
<input type="checkbox"/>	Hearing Protection	
<input type="checkbox"/>	Respirator	
<input type="checkbox"/>	Safety Shoes	R
<input type="checkbox"/>	Rubber Boots	
<input type="checkbox"/>	Leather Gloves	
<input type="checkbox"/>	Chemical Gloves	
<input type="checkbox"/>	Coveralls	
<input type="checkbox"/>	Tyvek	
<input type="checkbox"/>	Safety Vest	
<input type="checkbox"/>	Other	

Inspector EMG Engineer GSPLast Onsite Compliance 11/14/2005

Contacted

Phone

Fax

E-mail

☐ Tom Craig Plant Manager remove

(206) 762-7170

☒ Eric Parantio Maint Supervisor

(206) 762-7171 ext 262

eeparantio@longfibre.com remove

☒ Bob Woods Maint Supervisor

(206) 762-7170

☒ Belton Rogers Plant Superintendent☒ Mike Anderson General Supervisor (206) 762-7170

North American Industrial Classification System (NAICS): 322211 - Corrugated and Solid Fiber Box Manufacturing

Evaluation Date: 10/4/06 14:40

Clean Air Reps: E. Gilpin

Evaluation Type: ☒ Onsite Compliance ☐ Onsite Observation ☐ Follow-up ☐ Administrative Task

Evaluation Summary: on-site compliance inspection wearing Agency ID. Contacted Mike Anderson. Source manufactures cardboard boxes. No VE from cyclone on roof. Boiler on line burning Natural gas. No NSPS boiler records were on-site. CSR for more info issued for NSPS records

Updates: ☐ AOD ☐ Equipment ☐ NOC ☐ Operating Status ☐ Owner/Name ☒ Other contact

Attachments: 10/25/06 Renewed oil & spec sheet 905 is < .05% daily natural gas usage log OK.

NOV/WW # Issued: CSR for more information

Other Action:

Evaluation Prepared by: *MM*

Date: 10/6/06

Onsite Compliance Evaluations (Last 3)**Eval Date Inspector Inspector Notes****NOV/WW**

11/14/2005	EMG		CSR - no violations. Good O&M logs. Update NC, Equip List.	
12/03/2004	EMG		W W 2-000342 OA 6264 # 5. 5.05(e) Update File. Update Equip List.	2-000342
12/10/2002	EMG	MM	Observed steam plume from boiler - on roof for presence of So. Park Odor. No odors observed.	

Onsite Observation Evaluations (Last 3) - None

Offsite Report Evaluations (Last 18 Months)

Eval Date	Engineer	Inspector	Report Type	Month	Year	Subpart	Stack Test CAS	Stack Test EU	NOV/WW
01/27/2006	GSP	EMG	NSPS			Dc			
08/26/2005	GSP	EMG	NSPS			Dc			

Onsite Complaint Evaluations (Last 3) - None

Violation History (Last 2 Years)

Issue Date	Issued By	NOV/WW	Violation Date	Closed?	Regulation Violations
12/03/2004	EMG	2-000342	12/03/2004	<input checked="" type="checkbox"/>	1 OA 6264 #5, 5.05 e

Open AOD Conditions - None

Notices of Construction / Notifications Evaluation Pending - None

Notices of Construction / Notifications**Inactive? NOC / Notice #****Approved Evaluated****GSP initials**

<input type="checkbox"/>	824	Cyclone On Shredder	09/29/1972	11/14/2005
<input type="checkbox"/>	6264	Boiler @ 25 Mmbtu/Hr	12/05/1995	08/02/1996

Conditions

4. Longview Fibre Co. (LFC) is subject to requirements of 40 CFR 60 Subpart Dc and shall notify EPA of the installation.
5. LFC shall operate these boilers using No. 2 oil with no more than 0.05% sulfur. Records shall be maintained for a period of two years and made available to PSAPCA personnel upon request.
6. Within 180 days of startup of the boilers, LFC shall perform a compliance test according to Regulation I, Section 3.07, to demonstrate compliance with the NOx and CO limits in Condition No. 7.
7. The emissions of this boiler shall not exceed any of the following: a. NOx = 0.05, CO = 0.05, SO2 = 0.01, VOC = 0.02 lb/MMBtu one-hour average on natural gas. b. NOx = 0.20, CO = 0.10, SO2 = 0.60, VOC = 0.05 lb/MMBtu one-hour average on No. 2 oil. c. PM-10 = 0.02 gr/dscf @ 7% O2. d. Source test methods are EPA Methods 6C for SO2, 7E for NOx, 10A for CO, and 25A for VOC; and PM-10 by PSAPCA procedure in Resolution 540 dated Aug 11, 1993.
8. It shall be unlawful for LFC to cause or allow the emission of any air contaminant from this boiler which exceeds 10% opacity according to EPA Method 9.

Description

One natural gas/No. 2 oil fired Cleaver-Brooks Boiler rated at 25.1 MMBtu/hr.

Air Contaminant Generating Equipment, Associated Control Equipment**Inactive?**

- | | | | | | |
|--------------------------|---------|---------------------------------------|----------------------|-----------|------|
| <input type="checkbox"/> | (1) | Boiler | | | |
| | | Cleaver Brooks | | | |
| | | Rated: 25 Million BTU/Hr | Year Installed: 1996 | NC/NOT #: | 6264 |
| | | Natural Gas / Dist (#2 Oil or PS-300) | | | |
| <input type="checkbox"/> | (2) | Storage Bin/Silo System | | | |
| | | NE Exterior Corn Starch Silo | | | |
| | | Rated: 55000 Lb | Year Installed: | NC/NOT #: | |
| <input type="checkbox"/> | *CE (2) | Baghouse | | | |
| | | On Top Of Silo 50 Bags | | | |
| | | Rated: 500 CFM | Year Installed: | NC/NOT #: | |

Air Contaminant Generating Equipment, Associated Control Equipment**Inactive?**☐ * (3) Paper Shredder
/baler☐ CE (1) Single cyclone
Paper Shredder And Presses

Rated: 42000 CFM Year Installed: 1972 NC/NOT #: 824

* This item does not require a Notice of Construction.

Other Control Equipment - None

Emission Summary - None for 2004 or 2005